



# **INSPECTION REPORT**

Inspector: Thomas Tripline Licensed # 34193

10000 Sample Road, Sample, MD 10000 Inspection prepared for: Sample Client Date of Inspection: 1/13/2022 Time: 10:00 AM Year Built: 1995 Size (Sqft): 2500 Weather: 34 Sunny Order ID: 9756







46179 Westlake Dr, Suite 200B, Sterling Va 20165



(703) 450-6398




INFO@NEXTDAYINSPECT.COM



WWW.NEXTDAYINSPECT.COM

#### Table Of Contents





#### Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expense to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all pages of the report as the summary alone does not explain all of the issues. All repairs should be done by a licensed & bonded tradesman or qualified professional. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

| Repair           |                            |   |
|------------------|----------------------------|---|
| Roof             |                            |   |
| Page 10 Item: 2  | Gutter                     | • Extensions/splash blocks missing or insufficient at one or more downspouts. Recommend installing a 6-feet extension to divert water away from the foundation.   |
| Page 12 Item: 4  | Flashing                   | • Previous repairs with mastic material around several flashing, recommend review and repair by a certified roofing specialist.   |
| Page 12 Item: 5  | Eave and rake              | <ul> <li>Rotted wood observed on the dormer rake edge.</li> <li>Recommend repair/replace as needed.</li> </ul>  |
| Grounds & Exter  | ior                        |   |
| Page 16 Item: 2  | Grading                    | <ul> <li>Several areas by the structure were low or had a negative grade. Recommend repair</li> </ul>   |
| Page 16 Item: 3  | Vegetation<br>Observations | • Prune or remove any plants that are in contact or proximity to home to eliminate pathways for wood destroying insects.  |
| Page 17 Item: 4  | Deck                       | <ul> <li>There is wood and soil contact at deck columns. Some wood deterioration was noted, repair as needed.</li> <li>Missing damaged balusters recommend repair/replacement by qualified contractor.</li> </ul>   |
| Page 21 Item: 9  | Cladding Condition         | <ul> <li>Rotting wood observed, suggest scraping, wood<br/>repair/replacing and painting as necessary by a qualified<br/>siding specialist</li> <li>Some areas need priming and repainting recommend repair<br/>by qualified contractor.</li> <li>Major cracks/gaps or holes noted at the brick wall and siding<br/>boards. Recommend repair/seal all gaps and holes to prevent<br/>water or moisture penetration to the wall structure.</li> </ul> |
| Page 22 Item: 10 | Window Condition           | <ul> <li>Deterioration, gaps and cracks noted at window frames<br/>and/or sills. Recommend repair and seal/caulk as needed.</li> </ul>  |
| Garage           |                            |   |
| Page 24 Item: 3  | Garage Opener<br>Status    | • Garage vehicle door opener didn't not operate at the time of inspection. Recommend repair/replace as needed.  |
| Interior Areas   |                            |   |
| Page 29 Item: 4  | Door Bell                  | <ul> <li>Damaged button. Replace as needed.</li> </ul>  |
| Kitchen          |                            |   |
| Page 31 Item: 5  | Window Condition           | <ul> <li>Screens were not installed at time of inspection.</li> <li>Recommend replacement</li> </ul>  |

| Page 32 Item: 9  | Counters                | • The counter tops appear to be worn and may have reached the end of their useful life. Recommend replacement  |
|------------------|-------------------------|--|
| Page 32 Item: 10 | Dishwasher              | <ul> <li>No high drain loop noted. Dishwasher high drain loop is to<br/>prevent back flow of water into the dishwasher.</li> </ul>   |
| Page 33 Item: 11 | Garbage Disposal        | • The disposal was not functional at the time of the inspection, repair/replace as needed.   |
| Attic            |                         |  |
| Page 40 Item: 1  | Access                  | • Access cover has no insulation. Recommended insulating the access cover to minimize the heat loss.   |
| 5                | Insulation<br>Condition | <ul> <li>Uninsulated areas observed. Recommend to insulate<br/>properly to reduce heat escape.</li> </ul>  |
| Water Heater     |                         |  |
| Page 48 Item: 7  | Base                    | • No drip pan and drain line noted. It's generally recommended to install a drip pan with a drain line beneath the water heater tank, recommend installation.                          |
| Bath-01          |                         |  |
| Page 57 Item: 3  | Doors                   | • The door sticking at the top maybe the door needs to be adjusted or shaving 1/8-1/4 inch. Recommend repair   |
| Page 60 Item: 17 | Bath Tubs               | • Whirlpool is inoperable, recommend review by a licensed plumber for repair or replacement, as necessary, prior to close.   |
| Page 61 Item: 18 | Toilets                 | <ul> <li>Gap between toilet base and floor noted. Recommend caulk/seal as needed.</li> <li>Toilet loose and may need re-anchoring.</li> </ul>  |
| Page 62 Item: 20 | Window Condition        | <ul> <li>Hardware difficult to operate at one or more locations.</li> <li>Recommend review and repair as needed by qualified window contractors.</li> </ul>                            |
| Bath-02          |                         |  |
| Page 66 Item: 17 | Toilets                 | • Gap between toilet base and floor noted. Recommend caulk/seal as needed.   |
| Bath-03          |                         |  |
| Page 68 Item: 8  | Electrical              | Light bulbs are not working or missing at some fixtures recommend replacement  |
| Page 69 Item: 11 | Counters                | • The counter tops appear to be worn and may have reached<br>the end of their useful life recommend replacement due to<br>stains.  |
| Page 70 Item: 14 | Toilets                 | <ul> <li>Gap between toilet base and floor noted. Recommend<br/>caulk/seal as needed.</li> </ul>   |
| Bath-04          |                         |  |
| Page 75 Item: 15 | Toilets                 | <ul> <li>Gap between toilet base and floor noted. Recommend caulk/seal as needed.</li> <li>Toilet loose and may need re-anchoring. Recommend repair by licensed contractor.</li> </ul> |
| Dinning Room     |                         |  |
| Page 82 Item: 5  | Window Condition        | Missing or damaged screen on several windows noted. Recommend installing screen.   |
|                  |                         | Page 4 of 105  |
|                  |                         |  |

| Family Room      | -                 |   |
|------------------|-------------------|---|
| Page 83 Item: 2  | Ceiling Condition | <ul> <li>Cracks on ceiling noted. Recommend repair as needed.</li> </ul>  |
| Page 84 Item: 4  | Floor Condition   | <ul> <li>Carpet stains observed on all house floors. Recommend<br/>clean/replace as needed.</li> </ul>                            |
| Rec Room         |                   |   |
| Page 88 Item: 2  | Doors             | • Damaged/broken frame on door observed. Recommend replacing the door frame.  |
| Page 89 Item: 5  | Floor Condition   | <ul> <li>Carpet ripples observed on all house floors. Recommend<br/>clean/replace as needed.</li> </ul>                           |
| Page 90 Item: 6  | Window Condition  | <ul> <li>Missing screen on several windows noted. Recommend installing screen.</li> </ul>   |
| BEDROOM-01       |                   |   |
| Page 94 Item: 5  | Floor Condition   | <ul> <li>Carpet in the Master bedroom Rippling, recommend repair<br/>or replace</li> </ul>  |
| BEDROOM-02       |                   |   |
| Page 95 Item: 2  | Doors             | <ul> <li>Bedroom door didn't latch when tested. Recommend repair<br/>as needed.</li> </ul>  |
| Page 96 Item: 5  | Floor Condition   | <ul> <li>Stains observed on the carpet. Recommend clean/replace<br/>as needed.</li> </ul>   |
| BEDROOM-03       |                   |   |
| Page 98 Item: 2  | Doors             | <ul> <li>Bedroom door didn't latch when tested. Recommend repair<br/>as needed.</li> </ul>  |
| Page 99 Item: 5  | Floor Condition   | <ul> <li>Carpet in the Master bedroom Rippling, recommend repair<br/>or replace</li> </ul>  |
| Page 99 Item: 6  | Window Condition  | <ul> <li>Damaged or missing screens observed. Recommend replacement</li> </ul>  |
| BEDROOM-04       |                   |   |
| Page 101 Item: 3 | Ceiling Condition | <ul> <li>Previous repair noted, inspector couldn't determine the<br/>cause of the damage or the quality of the repair.</li> </ul> |

| Monitor<br>Water Heater |          |  |
|-------------------------|----------|--|
| Page 47 Item: 4         | Plumbing | <ul> <li>Corrosion observed. No active leak noted. Monitor for<br/>worsening corrosion.</li> </ul> |
| BEDROOM-02              | •        |  |
| Page 95 Item: 4         |          | <ul> <li>Minor crack in the wall corner. We recommend<br/>monitor/repair if gaps widen.</li> </ul> |

| Safety                  |                                   |   |
|-------------------------|-----------------------------------|---|
| Grounds & Exter         | ior                               |   |
| Page 15 Item: 1         | Driveway and<br>Walkway Condition | • Uneven slabs at the garage entrance This is a potential tripping hazard. Recommend repair and or replacement of the displaced section.  |
| Page 19 Item: 5         | Stairs & Handrail                 | <ul> <li>Loose handrail noted. Recommend repair/secure as needed<br/>for safety.</li> </ul>   |
| Garage                  | -                                 |   |
| Page 26 Item: 7         | Electrical                        | <ul> <li>Recommend upgrading ALL receptacle to GFCI protection<br/>within 6 feet of all potential wet locations, garage, and exterior<br/>withing 7 ft from ground for safety.</li> </ul> |
| Attic                   | -                                 |   |
| Page 42 Item: 6         | Electrical                        | • Electric wires on top of joists. For safety, the wires should be routed through the joists or rerouted to attic areas with less than 18" head clearance.                                |
| Bath-01                 |                                   |   |
| Page 58 Item: 9         | GFCI                              | <ul> <li>GFCI did not respond to test, suggest replacing for safety.</li> </ul>   |
| Bath-02                 | -                                 |   |
| Page 64 Item: 9         | GFCI                              | <ul> <li>GFCI did not respond to test, suggest replacing for safety.</li> </ul>   |
| Bath-03                 | -                                 |   |
| Page 69 Item: 9         | GFCI                              | <ul> <li>GFCI did not respond to test, suggest replacing for safety.</li> </ul>   |
| <b>Upstairs Hallway</b> | 1                                 |   |
| Page 87 Item: 7         | Smoke Detectors                   | <ul> <li>Old detectors. Smoke detectors last 6-10 years.<br/>Recommend replacing for safety.</li> </ul>   |
| Rec Room                |                                   |   |
| Page 90 Item: 6         | Window Condition                  | <ul> <li>Mold-like bio growth observed. Professional testing &amp; evaluation advised for safety.</li> </ul>  |
| Page 90 Item: 7         | Electrical                        | <ul> <li>Missing several outlet covers. Recommend replacement for<br/>safety</li> </ul>   |
| Page 90 Item: 8         | Smoke Detectors                   | <ul> <li>Old detectors. Smoke detectors last 6-10 years.<br/>Recommend replacing.</li> </ul>  |
| BEDROOM-03              |                                   |   |
| Page 98 Item: 2         | Doors                             | <ul> <li>Loose door handle noted, repair/replace as needed for<br/>safety.</li> </ul>   |

| Maintenance<br>HVAC Zone 1 |   |
|----------------------------|---|
| Page 52 Item: 4            | • HVAC system service date was over 12 months or not being able to be determined. We recommend the HVAC system be serviced and cleaned by a licensed HVAC specialist. |

| Family Room     |  |
|-----------------|--|
| Page 84 Item: 5 | <ul> <li>Level II inspection—The National Fire Protection Association<br/>(www.nfpa.org) recommend that each chimney receive a<br/>Level II inspection each time a residence is sold.</li> </ul> |

# **INTRODUCTION:**

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire closing process.

Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFCI outlets may not be installed; this report will focus on safety and function, not current code. This report identifies specific non-code, non-cosmetic concerns that the inspector feels may need further investigation or repair.

For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

# **Inspection Details**

# 1. Attendance

In Attendance: Client present • Buyer Agent present

#### 2. Home Type

Home Type: Detached • Single Family Home • Ranch Style

# 3. Occupancy

Occupancy: Vacant • The utilities were on at the time of inspection. • ACCESS TO SOME ITEMS SUCH AS: ELECTRICAL OUTLETS, WINDOWS, WALL/FLOOR SURFACES, AND CABINET INTERIORS WAS RESTRICTED BY FURNITURE AND LARGE QUANTITY OF PERSONAL BELONGINGS. ANY SUCH ITEMS ARE EXCLUDED FROM THIS INSPECTION REPORT. • Some breakers turned off some appliances not inspected due to no power at the time of inspection.

|  | R  | Roof |                                      |
|--|--|------|--------------------------------------|
| 1. Roof Condit                             | ion  |      |                                      |
| Good Fair Poor N                           | Materials: Inspected from g<br>Some areas of the roof ma<br>Inspected from ground leve<br>visually restricted from insp<br>ice and snow at the time of |      | on. •<br>roof may be<br>covered with |
| Asphalt Shingles<br>Tiles<br>Metal Roofing | 20 years<br>50 - 80 years  |      |                                      |
| Slate                                      | 75 - 100+ years  |      |                                      |



#### 2. Gutter


Wood

30 years



Observations: • Extensions/splash blocks missing or insufficient at one or more downspouts. Recommend installing a 6-feet extension to divert water away from the foundation.





# 3. Vent Stack

| Good | Fair | Poor | N/A | None |   |
|------|------|------|-----|------|---|
| ✓    |      |      |     |      | <ul><li>Observations:</li><li>Appeared to be in good condition at the time of inspection.</li></ul> |



# 4. Flashing

| Good | Fair  | Poor | N/A | None |   |
|------|---|------|-----|------|---|
|      |   |      |     |      | Observations:   |
|      | <ul> <li>Image: A start of the start of</li></ul> |      |     |      | Observations:<br>• Previous repairs with mastic material around several flashing, recommend |
|      |   |      |     |      | review and repair by a certified roofing specialist.  |



#### 5. Eave and rake



Observations: • Rotted wood observed on the dormer rake edge. Recommend repair/replace as needed.





#### 6. Chimney Good Fair Poor



None

Observations: • No major system safety or function concerns noted at the time of inspection.



# 7. Spark Arrestor



Observations: • Appeared in good condition at the time of inspection.







#### 2. Grading



Observations: • Several areas by the structure were low or had a negative grade. Recommend repair



# Negative grading

# 3. Vegetation Observations



Observations: • Maintenance Tip: When landscaping, keep plants, even at full growth, at least a foot (preferably 18 inches) from house siding and windows. Keep

trees away from foundation and roof. Plants in contact or proximity to home can provide pathways for wood destroying insects, as well as abrade and damage siding, screens and roofs.

• Prune or remove any plants that are in contact or proximity to home to eliminate pathways for wood destroying insects.






Vegetation against cladding (noted)



Vegetation on cladding






Wood soil contact (noted)





Loose



#### 5. Stairs & Handrail Good Fair Poor N/A None



Observations: • Loose handrail noted. Recommend repair/secure as needed for safety.







Loose balusters



Loose

Page 19 of 105



None



# 6. Patio




Observations: • Recommend cleaning off all vegetation off patio areas to inhibit further damages and deterioration.









• Major cracks/gaps or holes noted at the brick wall and siding boards. Recommend repair/seal all gaps and holes to prevent water or moisture penetration to the wall structure.

Page 21 of 105



**10. Window Condition** 

Good Fair Poor N/A None Observations:

• Deterioration, gaps and cracks noted at window frames and/or sills. Recommend repair and seal/caulk as needed.

Page 22 of 105



# 11. Doors



Observations: • Appeared in functional condition at the time of inspection.



#### Garage

# **1. General Condition**

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
|      | 1    |      |     |      |

Materials: Attached 2-car garage


Observations:

• Accessible in general, acceptable condition, some areas are not accessible.





### 2. Garage Door Condition



Materials: One 16' upgraded insulated steel door

- Observations:
- No deficiencies observed at the time of the inspection.

# 3. Garage Opener Status




Observations:

Chain drive opener.


• Garage vehicle door opener didn't not operate at the time of inspection. Recommend repair/replace as needed.



### 4. Exterior Door



None Observations: • Appeared functional at the time of inspection.



## 5. Fire Door



- Observations: Appeared satisfactory and functional, at time of inspection. Garage door appeared to be fire rated.



# 6. Floor Condition




Materials: Concrete floors.

Observations: • Limited view due to stored personal items and/or parked vehicles in the garage.



# 7. Electrical







No GFCI

#### **Interior Areas**

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.




#### 2. Window Condition



Materials: Vinyl • Single Hung Windows • double pane

Observations:

• Thermal imaging did not show significant energy loss at the time of the inspection.



#### Next Day Inspect



#### 3. Smoke Detectors



Observations:

• MAINTENANCE: Periodic testing and changing batteries yearly to ensure proper Smoke Alarm operation is required.

• Testing of smoke detectors is not included in this inspection. Pushing the "Test" button only verifies that there is power at the detector--either a battery or hard wired to the house power--and not the operational workings of the detector. The operational check is done by filling the sensor with smoke and is beyond the scope of this inspection. Battery operated smoke alarms should be checked routinely and the batteries changed frequently.

#### 4. Door Bell

| _ | Good | Fair | Poor | N/A | None | _ |
|---|------|------|------|-----|------|---|
|   |      |      | 1    |     |      |   |

Observations: • Damaged button. Replace as needed.



Damaged

Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

# 1. Condition





# 2. Ceiling Condition

| Good | ⊦aır | Poor | N/A |
|------|------|------|-----|
|      |      |      |     |
| 1    |      |      |     |
| v    |      |      |     |
|      |      |      |     |

Materials: Drywall ceilings.

Observations:

• No signs of damage or leaks at the time of inspection.


### 3. Wall Condition





Materials: Drywall. • Wall paper finish noted.

Observations:

• Walls were in good shape at time of inspection







#### 11. Garbage Disposal Good Fair Poor N/A None

1





# 12. Sinks



Observations: • Sink appeared to be in good condition at the time of inspection..




# **13. Plumbing** Good Fair Poor N/A



Observations: • No active leaks in supply or drain lines observed at the time of inspection. • No deficiencies noted.




# 14. Cooktop condition



Electric cooktop noted.Not inspected no power at the time of inspection.



#### 15. Oven & Range Good Fair Poor N/A None



# 16. Refrigerator Condition

Good Fair Poor N/A None

Observations: • Unit was not tested, no power at the time of inspection.






Power Off

| Next Day Inspect  |
|---|
| Laundry 1. General View Condition   |
| Good Fair Poor N/A None Materials: Main Level Observations:<br>• Functional   |
|   |
| 2. Doors  |
| Good Fair Poor N/A None Observations:<br>✓  |
| 3. Floor Condition  |
| Materials: Ceramic tiles.<br>Materials: Ceramic tiles.<br>Observations:<br>• Flooring appeared in good condition at the time of inspection. |
| 4. Wall Condition   |
| Good Fair Poor N/A None<br>Materials: Drywall.<br>Observations:<br>• No deficiencies observed at the time of inspection.                    |
| 5. Ceiling Condition  |
| Good Fair Poor N/A None<br>✓ Materials: Drywall ceilings.<br>Observations:<br>• Appeared in good shape at the time of inspection.           |
| 6. Washer   |
| Good Fair Poor N/A None Observations:<br>• Appeared functional at the time of inspection.   |
|   |
|   |
|   |
|   |

Page 37 of 105





Observations: • Appeared functional at the time of inspection.



# 8. Drver Vent

| ( | Good | Fair | Poor | N/A | None |   |
|---|------|------|------|-----|------|---|
|   | <    |      |      |     |      | Observations:<br>• No deficiencies noted. |




#### 9. Plumbing Good Fair Poor



Observations: • Appeared to be in good shape at the time of inspection, access limited.





#### Next Day Inspect



#### 3. Insulation Condition



Materials: Blown in cellulose insulation noted.

Depth: Insulation averages about 4-6 inches in depth; more recommended. Observations:

• Uninsulated areas observed. Recommend to insulate properly to reduce heat escape.





#### 4. Ventilation



Observations:

- Soffit and ridge vent.
- Gable louver vents noted.

• Ventilation appears to be in satisfactory condition at the time of the inspection.





#### 5. Vent Screens

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
|      |      |      |     |      |
| v    |      |      |     |      |

Observations: • Vent screens noted as functional.


#### 6. Electrical

| Good | Fair | Poor | N/A | None |
|------|------|------|-----|------|
|      |      | ~    |     |      |


Observations: • Electric wires on top of joists. For safety, the wires should be routed through the joists or rerouted to attic areas with less than 18" head clearance.











HI








#### 7. Base



Observations:

• No drip pan and drain line noted. It's generally recommended to install a drip pan with a drain line beneath the water heater tank, recommend installation.







# 4. Water & Sewer System



ן Materials: Public Water

#### HVAC Zone 1

# 1. AC Compress Condition

Compressor Type: Electric

Location: The compressor is located on the side yard.

Observations:

• NOTE: Unit(s) not tested in the cooling mode. A/C units should not be operated when the ambient temperature is below 65°F as damage to the unit could occur. This test is excluded from the scope of this inspection due to the ambient temperature.

• Manufacture date: (2016). Life expectancy around 20 years.





#### 2. Refrigerant Lines








| 3. Thermostats      |  |
|---------------------|--|
|                     | Observations:<br>Digital - programmable type.<br>Functional at the time of inspection.<br>Thermostats are not checked for calibration or timed functions.<br>Recommend that the client(s) have the homeowner provide the instructions<br>or programming or show the client(s) how to do so.  |
| 1 Upster Osmilition |  |
| 4. Heater Condition | acation: The Heat nump is located in the basement  |
|                     | Location: The Heat pump is located in the basement<br>Type: Electric forced hot air. • Heat pump noted.<br>Observations:   |
| t<br>•<br>c         | <ul> <li>Unit appeared to operate properly using normal operating controls at the ime of inspection.</li> <li>Manufacture date:(2014). Life expectancy around 20 years.</li> <li>HVAC system service date was over 12 months or not being able to be determined. We recommend the HVAC system be serviced and cleaned by a icensed HVAC specialist.</li> </ul> |
|                     |  |

| 5. Filters   |
|--|
| Good       Fair       Poor       NA       None         Image: Cool       Image: Cool       Description:       Location: Located at the bottom of cabinet.         Observations:       Pilters appeared clean at the time of inspection.       HalNTENANCE: The air filter(s) should be inspected at least monthly and cleaned or replaced as required. Remember that dirty filters are the most common cause of inadequate heating or cooling performance.         Image: Cool       Image: Cool       Image: Cool         Image |
|  |
| <ul> <li>6. Venting</li> <li>Good Fair Poor N/A None Observations:</li> <li> <ul> <li></li></ul></li></ul>   |
| 7. Enclosure   |
| Good Fair Poor N/A None Observations:  |
|  |
| 8. Enclosure Base  |
| Good Fair Poor N/A None Observations:<br>• The heater base appeared to be functional.  |

# Next Day Inspect



#### 9. Air Supply




#### 10. Registers

| Fair | Poor | N/A       | None          |
|------|------|-----------|---------------|
|      |      |           |               |
|      | Fair | Fair Poor | Fair Poor N/A |


Observations: • Functional and achieved adequate differential temperature between supply and return air.








Heating return





Observations: • Appeared functional and in good condition.



# **Radon Unit Placement**


# 1. Radon Placement




Materials: Basement

Observations:
 Continuous reading Corentium ------







#### 9. GFCI

| Good | Fair | Poor |   |
|------|------|------|---|
|      |      | 1    | Γ |

N/A

None

None

Observations: • GFCI did not respond to test, suggest replacing for safety.





No GFCI

## 10. Cabinets

| Good | Fair | Poor | N/A |
|------|------|------|-----|
|      | 1    |      |     |

Observations: • No deficiencies observed.

#### 11. Counters

| _ | Good | Fair | Poor | N/A | None |  |
|---|------|------|------|-----|------|--|
|   | <    |      |      |     |      |  |
| L |      |      |      |     |      |  |

Observations: Solid surface counter-tops.
No deficiencies observed.

### 12. Sinks

Good Fair Poor N/A None ✓

- Observations:
- No deficiencies observed.
- \*\*SUPPLY\*\*
- Operated normally at the time of inspection.



# **13. Plumbing** Good Fair Poor N/A None Observations: ✓ All fixtures te

• All fixtures tested and operated normally. No functional or safety concerns noted at the time of inspection.




#### 14. Showers

| Good | Fair | Poor | N/A | None |               |
|------|------|------|-----|------|---------------|
|      |      |      |     |      | Observations: |
| ✓    |      |      |     |      | Functional.   |



### 15. Shower Walls





# Good Fair Poor N/A None




Observations: • The shower enclosure was functional at the time of the inspection.





# 17. Bath Tubs



Whirlpool
Whirlpool is inoperable, recommend review by a licensed plumber for repair or replacement, as necessary, prior to close.



#### **18. Toilets** Good Fair Poor



Observations: • Gap between toilet base and floor noted. Recommend caulk/seal as needed.

• Toilet loose and may need re-anchoring.






Not anchored

# Next Day Inspect



#### **19. Mirrors**



### 20. Window Condition

| Good | Fair | Poor | N/A | None | Type: Vinyl • Casement Windows • Double pane<br>Observations:              |
|------|------|------|-----|------|--|
|      |      |      |     |      | I ype: Vinyi • Casement Windows • Double pane                              |
|      |      |      |     |      | Observations:  |
|      |      |      |     |      | • Hardware difficult to operate at one or more locations. Recommend review |
|      |      |      |     |      |  |
|      |      |      |     |      | and repair as needed by qualified window contractors.                      |



| Next Day Inspect  |
|---|
| Bath-02   |
| 1. Locations  |
| Locations: First Floor  |
| 2. General View   |
| Good Fair Poor NA None<br>✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓   |
|   |
| 3. Doors  |
| <ul> <li>Good Fair Poor N/A None Observations:</li> <li>✓ Observations:</li> <li>• The doors were functional and latched properly at the time of inspection.</li> </ul> |
| 4. Floor Condition  |
| Good Fair Poor N/A None Materials: Ceramic tile.<br>✓ Observations:<br>• No deficiencies observed at the time of inspection.  |
| 5. Walls Condition  |
| Good Fair Poor N/A None<br>✓  |
| 6. Ceiling Condition  |
| Good Fair Poor N/A None<br>✓ Materials: Drywall ceilings.<br>Observations:<br>• No major deficiencies or concerns noted at the time of inspection.                      |
| 7. Exhaust Fan  |
| Good Fair Poor N/A None Observations:<br>✓                             • The exhaust fan operated normal at the time of the inspection.                                 |
| 8. Electrical   |
| Good Fair Poor N/A None<br>✓ Observations:<br>• No major system safety or function concerns noted at the time of inspection.  |
| Page 63 of 105  |

#### 9. GFCI

| · · | · |
|-----|---|

Observations: • GFCI did not respond to test, suggest replacing for safety.



None

None



No GFCI

### 10. Cabinets

| Good | Fair | Poor | N/A |
|------|------|------|-----|
|      |      |      |     |
| ✓    |      |      |     |

Observations: • No deficiencies observed.

#### 11. Counters

| Good | Fair | Poor | N/A | None | _ |
|------|------|------|-----|------|---|
| ~    |      |      |     |      |   |

Observations:


Solid surface counter-tops.
No deficiencies observed.

### 12. Sinks

Good Fair Poor N/A None ✓


- Observations:
- No deficiencies observed.
- \*\*SUPPLY\*\*
- Operated normally at the time of inspection.







#### 16. Bath Tubs



• Bathtubs appeared in good condition, water supply appeared adequate, and drainage was functional at the time of inspection.



#### 17. Toilets Fair

1

Poor

N/A

Good



• Gap between toilet base and floor noted. Recommend caulk/seal as needed.




1


Page 67 of 105

| Next Day Inspect  |
|---|
| Bath-03 1. Locations  |
|   |
| Locations: First Floor  |
| 2. General View   |
| Good       Fair       Poor       NA       Nome         • Functional, repairs recommended  |
| 3. Doors<br>Good Fair Poor N/A None Observations:   |
| <ul> <li>✓ Observations.</li> <li>• The doors were functional and latched properly at the time of inspection.</li> </ul>                              |
| 4. Floor Condition  |
| Materials: Ceramic tile.<br>Materials: Ceramic tile.<br>Observations:<br>• No deficiencies observed at the time of inspection.                        |
| 5. Walls Condition  |
| Materials: Drywall walls.<br>Materials: Drywall walls.<br>Observations:<br>• No major deficiencies or concerns noted at the time of inspection.       |
| 6. Ceiling Condition  |
| Materials: Drywall ceilings.<br>Observations:<br>• No major deficiencies or concerns noted at the time of inspection.                                 |
| 7. Exhaust Fan  |
| Good Fair Poor N/A None Observations:<br>✓                                 Observations:<br>• The bathroom fan was operated and no issues were found. |
| 8. Electrical   |
| Good Fair Poor NA None<br>✓ Observations:<br>• Light bulbs are not working or missing at some fixtures recommend<br>replacement                       |
| Page 68 of 105  |

| <image/>  |     |
|---|-----|
| 9. GFCI   |     |
| Good Fair Poor N/A None Observations:<br>• GFCI did not respond to test, suggest replacing for safety.  |     |
| 10. Cabinets  |     |
| Good Fair Poor N/A None Observations:<br>✓                             Observations:<br>• No deficiencies observed.   |     |
| 11. Counters  |     |
| Good Fair Poor N/A None<br>Solid surface counter-tops.<br>• The counter tops appear to be worn and may have reached the end of the useful life recommend replacement due to stains. | əir |
| 12. Sinks   |     |
| Good       Fair       Poor       N/A       Nome         V       I       I       I       IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII  |     |








| 5. Walls Condition                        |   |
|---|---|
| Good Fair Poor N/A None                   | Materials: Drywall walls.   |
|   | Observations:<br>No major deficiencies or concerns noted at the time of inspection.                 |
| 6. Ceiling Condition                      |   |
| Good Epir Poor N/A Nono                   | Materials: Drywall ceilings.  |
|   | Observations:   |
|   | No major deficiencies or concerns noted at the time of inspection.                                  |
| 7. Exhaust Fan<br>Good Fair Poor N/A None |   |
|   | Observations:   |
|   | The bathroom fan was operated and no issues were found.   |
| 8. Electrical                             |   |
|   | Observations:   |
|   | <ul> <li>No major system safety or function concerns noted at the time of<br/>nspection.</li> </ul> |
| 9. GFCI                                   |   |
| Cood Fair Dear N/A Name                   | Observations:   |
|   | GFCI in place and operational.  |
|   |   |
| 10. Sinks                                 |   |
| Good Fair Poor N/A None                   | Observations:   |
|   | No deficiencies observed. **SUPPLY**  |
|   | • Operated normally at the time of inspection.  |
|   |   |
|   |   |
|   |   |
|   |   |
|   |   |
|   |   |



### **11. Plumbing** Good Fair Poor N/A



Observations: • All fixtures tested and operated normally. No functional or safety concerns noted at the time of inspection.




### Next Day Inspect

| 12. Showers   |
|---|
| Good Fair Poor N/A None   |
|   |
|   |
| 13. Shower Walls  |
|   |
| ✓ I I I Ceramic tile.   |
| Observed in good condition at the time of the inspection, recommend periodic checking for gaps in the grout and seal as needed. |
|   |
| 14. Shower Door   |
| Good Fair Poor N/A None Observations:<br>✓ • The shower enclosure was functional at the time of the inspection.                 |
| 15. Toilets   |
| Good Fair Poor N/A None Observations:   |
| • Gap between toilet base and floor noted. Recommend caulk/seal as needed.  |
| <ul> <li>Toilet loose and may need re-anchoring. Recommend repair by licensed contractor.</li> </ul>                            |
| Page 75 of 105  |





Missing seal



Not anchored

|  | Foyer Entrance Area  |
|--|--|
| Materials: Man Level Observations: • Acceptable                       | 1. General View Condition  |
| Bood       Fair       Poor       NA       New         All doors and locks appeared functional and operated normally at the time of inspection.         Bood       Fair       Poor       NA       New         All doors and locks appeared functional and operated normally at the time of inspection.         Bood       Fair       Poor       NA       New         Acting Condition       Materials: Drywall ceilings.       Observations:       Observations:         Acting appeared to be in good condition at the time of inspection.       Observations:       Observations:         Acting appeared to be in good condition at the time of inspection.       Observations:       Observations:         Appeared to be in good condition at the time of inspection.       Observations:       Observations:         Appeared to be in good condition at the time of inspection.       Observations:       Observations:         Appeared to be in good condition at the time of inspection.       Observations:       Observations:         Appeared to be in good condition at the time of inspection.       Observations:       Observations:         Appeared to be in good condition at the time of inspection.       Observations:       Observations:         Appeared to be in serviceable condition at the time of inspection.       Observations:       Observations:         Boot       Fair | ✓ Materials: Main Level<br>Observations:   |
| 300d       Fair       Poor       NA       None         ✓       ✓       ✓       ✓       ✓         300d       Fair       Poor       NA       None         Atterials:       Drywall.       Wall paper finish noted.       Observations:         • Appeared to be in good condition at the time of inspection.       Observations:       • Appeared to be in good condition at the time of inspection.         5.       Floor       Condition:       • Alterials: Ceramic tile floors.       Observations:         • Flooring appeared in serviceable condition at the time of inspection.       • Flooring appeared in serviceable condition at the time of inspection.         5.       Electrical       O   |  |
| ✓       ✓       Observations:         • All doors and locks appeared functional and operated normally at the time of inspection.         Bood       Fair       Poor       NA         V       Image: Second tion       Materials: Drywall ceilings.<br>Observations:       • Ceiling appeared to be in good condition at the time of inspection.         • Wall Condition       • Ceiling appeared to be in good condition at the time of inspection.         • Wall Condition       Materials: Drywall. • Wall paper finish noted.<br>Observations:         • Appeared to be in good condition at the time of inspection.         • Appeared to be in good condition at the time of inspection.         • Appeared to be in good condition at the time of inspection.         • Appeared to be in good condition at the time of inspection.         • Appeared to be in good condition at the time of inspection.         • Appeared to be in serviceable condition at the time of inspection.         • Floor Condition         • Flooring appeared in serviceable condition at the time of inspection.         • Flooring appeared in serviceable condition at the time of inspection.         • Flooring appeared in serviceable condition at the time of inspection.         • Flooring appeared in serviceable condition at the time of inspection.   | 2. Doors   |
| 300d       Fair       Poor       N/A       None         ✓       ✓       ✓       ✓       ✓         300d       Fair       Poor       N/A       None         ✓       ✓       ✓       ✓       ✓         300d       Fair       Poor       N/A       None         ✓       ✓       ✓       ✓       ✓         ✓       ✓       ✓       ✓       ✓         ✓       ✓       ✓       ✓       ✓         300d       Fair       Poor       N/A       None         Materials: Drywall.       • Wall paper finish noted.       Observations:         • Appeared to be in good condition at the time of inspection.       Observations:         • Appeared to be in good condition at the time of inspection.       Observations:         • Appeared in serviceable condition at the time of inspection.       Observations:         • Flooring appeared in serviceable condition at the time of inspection.       •         S. Electrical       Servations:       •         300d       Fair       Poor       N/A         Year       Observations:       •       •         •       •       •       •       •         •<   | <ul> <li>Observations:</li> <li>• All doors and locks appeared functional and operated normally at the time</li> </ul> |
| 300d       Fair       Poor       N/A       None         ✓       ✓       ✓       ✓       ✓         300d       Fair       Poor       N/A       None         ✓       ✓       ✓       ✓       ✓         300d       Fair       Poor       N/A       None         ✓       ✓       ✓       ✓       ✓         ✓       ✓       ✓       ✓       ✓         ✓       ✓       ✓       ✓       ✓         300d       Fair       Poor       N/A       None         Materials: Drywall.       • Wall paper finish noted.       Observations:         • Appeared to be in good condition at the time of inspection.       Observations:         • Appeared to be in good condition at the time of inspection.       Observations:         • Appeared in serviceable condition at the time of inspection.       Observations:         • Flooring appeared in serviceable condition at the time of inspection.       •         S. Electrical       Servations:       •         300d       Fair       Poor       N/A         Year       Observations:       •       •         • Flooring appeared in serviceable condition at the time of inspection.       •  | 3. Ceiling Condition   |
| Wall Condition     Materials: Drywall. • Wall paper finish noted.     Observations:     • Appeared to be in good condition at the time of inspection.     • Appeared to be in good condition at the time of inspection.     • Appeared to be in good condition at the time of inspection.     • Appeared to be in good condition at the time of inspection.     • Appeared to be in good condition at the time of inspection.     • Appeared to be in good condition at the time of inspection.     • Appeared to be in good condition at the time of inspection.     • Floor Condition     • Appeared in serviceable condition at the time of inspection.     • Flooring appeared in serviceable condition at the time of inspection.   | Good Fair Poor N/A None Materials: Drywall ceilings.<br>✓ Observations:  |
| <ul> <li>Good Fair Poor N/A None Materials: Drywall. • Wall paper finish noted.</li> <li>Observations:</li> <li>• Appeared to be in good condition at the time of inspection.</li> <li><b>5. Floor Condition</b></li> <li>Good Fair Poor N/A None Materials: Ceramic tile floors.</li> <li>Observations:</li> <li>• Flooring appeared in serviceable condition at the time of inspection.</li> <li><b>6. Electrical</b></li> <li>Good Fair Poor N/A None Observations:</li> </ul>  |  |
| Floor Condition     Materials: Ceramic tile floors.     Observations:     Flooring appeared in serviceable condition at the time of inspection.     Electrical     Observations:     Observations:     Observations:   | Good Fair Poor N/A None Materials: Drywall. ● Wall paper finish noted.   |
| <ul> <li>Good Fair Poor N/A None Materials: Ceramic tile floors.<br/>Observations:<br/>• Flooring appeared in serviceable condition at the time of inspection.</li> <li><b>5. Electrical</b></li> <li>Good Fair Poor N/A None Observations:</li> </ul>   | Appeared to be in good condition at the time of inspection.  |
| Materials: Ceramic tile floors.<br>Observations:<br>• Flooring appeared in serviceable condition at the time of inspection.<br><b>5. Electrical</b>  | 5. Floor Condition   |
| Good Fair Poor N/A None Observations:  | ✓ Materials: Ceramic tile floors.<br>Observations:   |
| Good Fair Poor N/A None Observations:  | 6. Electrical  |
|  | Good Fair Poor N/A None Observations:  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |





Observations: • The closets were in serviceable condition at the time of inspection.



• Flooring appeared in serviceable condition at the time of inspection.

| Good Fair Poor N/A None | n<br>- Matarialau Vinula Cingla Llung Windows a dauble non a                                |
|-------------------------|---|
| ✓                       | Materials: Vinyl • Single Hung Windows • double pane<br>Observations:                       |
| •                       | • All tested windows were functional.   |
|                         |   |
| 6. Electrical           |   |
| Good Fair Poor N/A None | Observations:<br>• All tested electrical outlets were functional at the time of inspection. |
|                         |   |

# **Dinning Room 1. General View Condition** Good Fair Poor N/A None Materials: Main Level Observations: Good Condition, Some repairs recommended 2. Ceiling Condition

| Good | Fair | Poor | N/A |
|------|------|------|-----|
|      |      |      |     |
|      |      |      |     |

Materials: Drywall ceilings. Observations:

- Ceiling appeared to be in good condition at the time of inspection.

### 3. Wall Condition

| Goo | l Fair | Poor | N/A | None | Materiales Drawell - Mallace and finish a starl                                 |
|-----|--------|------|-----|------|---|
|     |        |      |     |      | Materials: Drywall. • Wall paper finish noted.                                  |
|     |        |      |     |      | Observations:   |
|     |        |      |     |      |   |
|     |        |      |     |      | <ul> <li>Appeared to be in good condition at the time of inspection.</li> </ul> |

### 4. Floor Condition



Materials: Carpeted floors. Observations:

• Flooring appeared in serviceable condition at the time of inspection.

| <ul> <li>5. Window Condition</li> <li>Good Fair Poor NA None</li> <li>Alterials: Vinyl • Single Hung Windows • double pane</li> <li>Observations:</li> <li>• All tested windows were functional.</li> <li>• Missing or damaged screen on several windows noted. Recommend</li> </ul> |
|--|
| <ul> <li>Materials: Vinyl • Single Hung Windows • double pane</li> <li>Observations:</li> <li>• All tested windows were functional.</li> <li>• Missing or damaged screen on several windows noted. Recommend</li> </ul>  |
|  |
| installing screen.   |
| Screen damaged   |
|  |
| 6. Electrical<br>Good Fair Poor N/A None   |
| • All tested electrical outlets were functional at the time of inspection.   |
|  |

### Family Room

### **1. General View Condition**




Observations: • Good Condition, Some repairs recommended



### 2. Ceiling Condition

| Good | Fair         | Poor | N/A | None | Materiale, Dravellasilians   |
|------|--------------|------|-----|------|--|
|      |              |      |     |      | Materials: Drywall ceilings.   |
|      | $\checkmark$ |      |     |      | Observations:  |
|      |              |      |     |      | <ul> <li>Cracks on ceiling noted. Recommend repair as needed.</li> </ul> |



Damaged

### 3. Wall Condition



Materials: Drywall. Observations: • Appeared to be in good condition at the time of inspection.





Materials: Vinyl • Single Hung Windows Observations: • All tested windows were functional.



## 7. Electrical



Observations: • All tested electrical outlets were functional at the time of inspection.



### **Upstairs Hallway 1. General View Condition** Good Fair Poor N/A None Materials: Main Level Observations: • Good Condition, Some repairs recommended 1 7 2. Doors Good Fair N/A Poor None Observations: • All doors and locks appeared functional and operated normally at the time of inspection. 3. Ceiling Condition Fair Poor N/A Good None Materials: Drywall ceilings. Observations: • Ceiling appeared to be in good condition at the time of inspection. 4. Wall Condition Good Fair Poor N/A None Materials: Drywall. • Wall paper finish noted. Observations: • Appeared to be in good condition at the time of inspection. 5. Floor Condition Fair Poor N/A None Good Materials: Carpeted floors. Observations: Flooring appeared in serviceable condition at the time of inspection. 6. Electrical Good Fair Poor N/A None Observations: • All tested electrical outlets were functional at the time of inspection.



### 7. Smoke Detectors



Observations:
MAINTENANCE: Periodic testing and changing batteries yearly to ensure proper Smoke Alarm operation is required.
Old detectors. Smoke detectors last 6-10 years. Recommend replacing for protection.

safety.



Tested

# Rec Room **1. General View Condition** Good Fair Poor N/A None Materials: Lowr Level 1 2. Doors Good Fair Poor N/A None Observations: • Damaged/broken frame on door observed. Recommend replacing the door frame. $\checkmark$



### 3. Ceiling Condition



Materials: Drywall ceilings.

Observations:

• Ceiling appeared to be in good condition at the time of inspection.

### 4. Wall Condition

| Good | Fair | Poor | N/A | None |    |
|------|------|------|-----|------|----|
|      |      |      |     |      | יו |
|      |      |      |     |      | (  |
|      |      |      |     |      |    |

Materials: Drywall.

Observations:

• Appeared to be in good condition at the time of inspection.

### 5. Floor Condition



Materials: Carpeted floors.

Observations: • Carpet ripples observed on all house floors. Recommend clean/replace as needed.



Ripples



Page 90 of 105



### 9. Stairs & Handrail



Observations: • Stairs and handrail appeared in good condition at the time of inspection.



### 10. Patio Doors



Observations: • The patio doors were functional during the inspection.





### **BEDROOM-01**





### 2. Doors

| Good | Fair | Poor |
|------|------|------|
|      |      |      |



Observations:

• The door was functional and latched properly at the time of inspection.

### 3. Ceiling Condition

| Good | Fair | Poor | N/A |
|------|------|------|-----|
|      |      |      |     |
|      |      |      |     |
| •    |      |      |     |

Materials: Drywall ceilings. Observations:

- No deficiencies or stains noted at the time of inspection.

### 4. Wall Condition




N/A


None


None

• No major defects noted at the time of inspection.

| Next Day Inspect  |
|---|
|   |
| 5. Floor Condition  |
| Good Fair Poor N/A None   |
| Flooring Types: Carpet.   |
| Carpet in the Master bedroom Rippling, recommend repair or replace  |
| 6. Window Condition   |
| Good Fair Poor N/A None Materials: Vinyl • Single Hung Windows • double pane  |
| ✓ I I Observations:   |
| • Operational and no deficiencies noted.  |
|   |
| 7. Electrical<br>Good Fair Poor N/A None<br>Observations:<br>All tested outlets in the hedroeme worked normally at the time of increation |
| • All tested outlets in the bedrooms worked normally at the time of inspection.   |
| 8. Closets<br>Good Fair Poor N/A None<br>✓ Observations:<br>• The closet was in serviceable condition.                                    |
|   |









### 7. Electrical



Observations: • All tested outlets in the bedrooms worked normally at the time of inspection.



### 8. Closets

| Good | Fair | Poor | N/A | None |     |
|------|------|------|-----|------|-----|
|      |      |      |     |      | טן  |
|      |      |      |     |      | • - |

bservations: The closet was in serviceable condition.



### 2. Doors

Good Fair Poor N/A None

Observations: • Bedroom door didn't latch when tested. Recommend repair as needed. • Loose door handle noted, repair/replace as needed for safety.

| Image: transformed by transformed b |
|--|
|  |
| 3. Ceiling Condition<br>Good Fair Poor N/A None<br>✓ Materials: Drywall ceilings.<br>Observations:<br>• No deficiencies or stains noted at the time of inspection.   |
| 4. Wall Condition  |
| Good Fair Poor N/A None Materials: Drywall.<br>Observations:<br>• No major defects noted at the time of inspection.  |
| 5. Floor Condition   |
| Good Fair Poor N/A None<br>Flooring Types: Carpet.<br>Observations:<br>• Carpet in the Master bedroom Rippling, recommend repair or replace  |
| 6. Window Condition  |
| Good       Fair       Poor       N/A       None         J       J       Descriptions:       Descriptions:         J       Descriptions:       Descriptions:       Descriptions:         J       Descriptions:       Descriptions:       Descriptions:         J       Descriptions:       Descriptions:       Descriptions:         Description:       Descriptions:       Descriptions:       Descriptions:         Description:       Description:       Descriptions:       Descriptions:         Description:       Description:       Description:       Description:   |

| 7. Electrical  |
|--|
| Good Fair Poor N/A None Observations:<br>All tested outlets in the bedrooms worked normally at the time of inspection. |
|  |
| 8. Closets   |
| Good Fair Poor N/A None Observations:  |

### **BEDROOM-04**

### **1. General View Condition**



None Materials: Basement

Observations: • Acceptable, some repairs needed






### 2. Doors

Fair

Good

N/A None Observations:



• The door was functional and latched properly at the time of inspection.

### 3. Ceiling Condition

Poor





Materials: Drywall ceilings. Observations:

• Previous repair noted, inspector couldn't determine the cause of the damage or the quality of the repair.



Damage previous repair (noted)







Observations: • The closet was in serviceable condition.

## **Inspection Type**

### 1. Inspection Limitations

| _ | Good | Fair | Poor | N/A | None |
|---|------|------|------|-----|------|
| I |      |      |      |     |      |
| 1 |      |      |      |     |      |
|   |      |      |      |     |      |

Materials: Residential Home Inspection

### Glossary

| Term      | Definition   |
|-----------|--|
| A/C       | Abbreviation for air conditioner and air conditioning  |
| Cellulose | Cellulose insulation: Ground-up newspaper that is treated with fire-retardant.   |
| GFCI      | A special device that is intended for the protection of personnel<br>by de-energizing a circuit, capable of opening the circuit when<br>even a small amount of current is flowing through the grounding<br>system. |
| PVC       | Polyvinyl chloride, which is used in the manufacture of white plastic pipe typically used for water supply lines.  |